Oil Field Environmental Incident Summary

Responsible Party: CONTINENTAL RESOURCES, INC. **Well Operator:** CONTINENTAL RESOURCES, INC.

Well Name: WHITMAN 11-34H

Field Name: OAKDALE Well File #: 17061

Date Incident:1/2/2016Time Incident:08:30Facility ID Number:County:DUNNTwp:147Rng:96Sec:34Qtr:

Location Description:

Submitted By: NATE STANHOPE Received By:

Contact Person: NATE STANHOPE

PO BOX 268870

OKLAHOMA CITY, OK 73126

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil 4 Barrels 4 Barrels

Brine

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

N/A

Areal Extent:

90 ft. x 60 ft. misted area on location

Potential Environmental Impacts:

Location soil

Action Taken or Planned:

All standing fluid in the flare pit was sucked up and returned to a tank on-site. All impacted snow/soil will be removed and replaced with clean fill.

Wastes Disposal Location: TBD

Agencies Involved: Doug Dolyniuk w/ NDIC

Updates

Date: 1/4/2016 Status: Reviewed - Assigned to Other Agency Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the release remained on location. NDIC retains oversight.